Cisco CCNACCNPCCIE Switches LAB inclusief SFP039s en Rack en (200 EUR)

Locatie **Noord-Holland, Amsterdam**
https://www.advertentiex.nl/x-863563-z

Te koop,

7 Cisco switches, die ik heb gebruikt om me voor te bereiden op mijn CCNP examen. Ik heb deze set samengesteld om met technieken zoals UDLD , HSRP , ROMMON/Password-Recovery , Multicast etc. te stoeien. Deze technieken werken namelijk niet/minder goed in Eve-NG of GNS3.

Compleet met console cable, SFP's + Fiber, power cables en rack mounts aan de zijkant.
Je kan deze set ook koppelen met een ESXi server die CSR1000V routers draait (dan heb je de INE CCIE R&S topology). Set bestaat uit 4x Cisco Catalyst 3750 en 3x Cisco Catalyst 2950

Eventueel kan ik je ook de CCNP boeken erbij doen (dit is wel voor de oude examens)

Output van de switches:Â

++

Switch# show ver
Cisco IOS Software, C3750 Software (C3750-IPBASEK9-M), Version 12.2(55)SE9, RELEASE SOFTWARE (fc1)
Technical Support:Â
Copyright (c) 1986-2014 by Cisco Systems, Inc.
Compiled Mon 03-Mar-14 02:24 by prod_rel_team
Image text-base: 0x[illegible] data-base 0x[illegible]

ROM: Bootstrap program is C3750 boot loader
BOOTLDR: C3750 Boot Loader (C3750-HBOOT-M) Version 12.2(44)SE5, RELEASE SOFTWARE (fc1)

Switch uptime is 2 minutes
System returned to ROM by power-on
System image file is "flash:/c3750-ipbasek9-mz.122-55.SE9.bin"

Cisco Switches SFP039s en Rack en CCNACCNPCCIE LAB inclusief https://www.advertentiex.nl/x-863563-z

This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at:

If you require further assistance please contact us by sending email to

cisco WS-C3750-24P (PowerPC405) processor (revision H0) with 131072K bytes of memory.
Processor board ID CAT1013R0WY
Last reset from power-on
1 Virtual Ethernet interface
24 FastEthernet interfaces
2 Gigabit Ethernet interfaces
The password-recovery mechanism is enabled.

512K bytes of flash-simulated non-volatile configuration memory.
Base ethernet MAC Address : 00:17:94:7B:B1:80
Motherboard assembly number : 73-9672-08
Power supply part number : 341-0029-04
Motherboard serial number : CAT10120BK4
Power supply serial number : LIT10060AQA
Model revision number : H0
Motherboard revision number : A0
Model number : WS-C3750-24PS-S
System serial number : CAT1013R0WY
Top Assembly Part Number : 800-25860-03
Top Assembly Revision Number : D0
Version ID : V04
CLEI Code Number : CNMV1K0CRC
Hardware Board Revision Number : 0x01

Switch Ports Model SW Version SW Image
------ ----- ----- ---------- ----------
3 26 WS-C3750-24P 12.2(55)SE9 C3750-IPBASEK9-M
Configuration register is 0xF

Switch#show ver
Cisco Internetwork Operating System Software
IOS (tm) C2950 Software (C2950-I6Q4L2-M), Version 12.1(22)EA2, RELEASE SOFTWARE (fc1)
Copyright (c) 1986-2004 by cisco Systems, Inc.
Compiled Sun 07-Nov-04 23:14 by antonino
Image text-base: 0x80010000, data-base: 0x8055E000

ROM: Bootstrap program is C2950 boot loader

Switch uptime is 3 minutes
System returned to ROM by power-on
System image file is "flash:c2950-i6q4l2-mz.121-22.EA2.bin"

cisco WS-C2950G-24-EI (RC32300) processor (revision L0) with 21055K bytes of memory.
Processor board ID FCZ0935Y25M
Last reset from system-reset
Running Enhanced Image
24 FastEthernet/IEEE 802.3 interface(s)
2 Gigabit Ethernet/IEEE 802.3 interface(s)

32K bytes of flash-simulated non-volatile configuration memory.
Base ethernet MAC Address: 00:15:2B:59:29:00
Motherboard assembly number: 73-7280-05
Power supply part number: 34-0965-01
Motherboard serial number: FOC09313UR3
Power supply serial number: PHI085002MA
Model revision number: L0
Motherboard revision number: A0
Model number: WS-C2950G-24-EI
System serial number: FCZ0935Y25M
Configuration register is