

Positiesensor MAZDA 2.3 2.0 1.8 16V BK12 SPORT AANBIEDING (16,94 EUR)



Locatie **Gelderland, Putten**
<https://www.advertentiex.nl/x-1508572-z>

Mazda 3 (BK12) [Sedan]
2.0i 16_V LF50; LF72 110 (150) 1999 02-2004 12-2008
Mazda 3 Sport (BK14) [Hatchback]
2.0i 16_V LF50; LF72 110 (150) 1999 10-2003 06-2009
Mazda 5 (CR19) [MPV]
1.8i 16_V L823 85 (116) 1798 03-2005 08-2010
2.0i 16_V LFF7 107 (145) 1999 03-2005 08-2010
Mazda 6 (GG12/82) [Sedan]
1.8i 16_V L813; L829 88 (120) 1798 08-2002 08-2007
2.0i 16_V LF17; LF18 104 (141) 1999 06-2002 08-2007
2.3i 16_V S-VT L333; L3C1; L3C9 122 (166) 2261 06-2002 08-2008
Mazda 6 Sport (GG14) [Hatchback]
1.8i 16_V L813; L829 88 (120) 1798 08-2002 09-2007
2.0i 16_V LF17; LF18 104 (141) 1999 08-2002 02-2005
2.3i 16_V S-VT L333; L3C1; L3C9 122 (166) 2261 08-2002 09-2007
Mazda 6 Sportbreak (GY19/89) [Combi]
2.0i 16_V LF17; LF18 104 (141) 1999 08-2002 02-2005
2.3i 16_V S-VT L333; L3C1; L3C9 122 (166) 2261 08-2002 09-2007
2.3i 16_V X-Drive L3V 119 (162) 2261 11-2002 09-2007
Mazda MPV (LW19/69) [FWD]

2.3.16 VL332; L3E9 104 (141) 2260 07-2002 02-2006
 2.3.16 VL332; L3E9 104 (141) 2260 07-2002 02-2006
 2.3.16 VL332; L3E9 104 (141) 2260 07-2002 02-2006



Positiesensor MAZDA 2.3 2.0
1.8 16V BK12 SPORT
AANBIEDING



Positiesensor MAZDA 2.3 2.0
1.8 16V BK12 SPORT
AANBIEDING



Positiesensor MAZDA 2.3 2.0
1.8 16V BK12 SPORT
AANBIEDING



Positiesensor MAZDA 2.3 2.0
1.8 16V BK12 SPORT
AANBIEDING



Positesensor MAZDA 2.3 2.0
1.8 16V BK12 SPORT
AANBIEDING



Positesensor MAZDA 2.3 2.0
1.8 16V BK12 SPORT
AANBIEDING



Positesensor MAZDA 2.3 2.0
1.8 16V BK12 SPORT
AANBIEDING



Positesensor MAZDA 2.3 2.0
1.8 16V BK12 SPORT
AANBIEDING



Positesensor MAZDA 2.3 2.0
1.8 16V BK12 SPORT
AANBIEDING



Positesensor MAZDA 2.3 2.0
1.8 16V BK12 SPORT
AANBIEDING