

Sony Xperia 1 II Defect




Locatie Gelderland, Wijchen
<https://www.advertentiax.nl/x-1932530-z>



Te koop aangeboden. Sony Xperia 1 II. Rechtsonder zit een beschadiging in het glas waardoor er een streep is ontstaan (zie foto's). Enkel de bovenste helft van het touchscreen functioneert. Verder is ook de oplaad connector aan vervanging toe. Al met al is het een opknapper of te gebruiken voor reserveonderdelen.

Verzending en ophalen.

 Sony Xperia 1 II Defect https://www.advertentiax.nl/x-1932530-z	 Sony Xperia 1 II Defect https://www.advertentiax.nl/x-1932530-z	 Sony Xperia 1 II Defect https://www.advertentiax.nl/x-1932530-z	 Sony Xperia 1 II Defect https://www.advertentiax.nl/x-1932530-z	 Sony Xperia 1 II Defect https://www.advertentiax.nl/x-1932530-z	 Sony Xperia 1 II Defect https://www.advertentiax.nl/x-1932530-z	 Sony Xperia 1 II Defect https://www.advertentiax.nl/x-1932530-z	 Sony Xperia 1 II Defect https://www.advertentiax.nl/x-1932530-z	 Sony Xperia 1 II Defect https://www.advertentiax.nl/x-1932530-z	 Sony Xperia 1 II Defect https://www.advertentiax.nl/x-1932530-z
--	---	---	---	--	---	---	---	---	---