

PIONEER AVIC-F70DAB defect, kabelsbezel Suzuki Celerio



Locatie **Noord-Brabant, Fijnaart**
<https://www.advertentiax.nl/x-1992045-z>

Defect, voor onderdelen. Er is water in het bedieningspaneel gekomen. Maar dit is een onafhankelijk uitschuifbare unit, dus ik ga ervanuit dat de speler zelf nog goed is. Maar geen enkele knop werkt, ook de aan/uit niet. LCD is mogelijk ook nog goed, in ieder geval niet mechanisch stuk.

Is toch wel jammer, was een dure en sjieke radio, met DAB, Navi, en Apple/Android Car. Er zit nu de originele FM radio weer in. Maar als je de Suzuki specifieke 2-din houder bezel wilt, dat is €10 extra, want dat is de enige wat ik mogelijk ooit nog zelf kan gerbuiken.

Kabels zitten erbij, en GPS antenne. Maar niet de DAB plakantenne, die komt natuurlijk nooit heel van de ruit.

Foto is een stock-foto van internet, maar als je dit koopt voor onderdelen weet je toch wel hoe het eruit.



PIONEER AVIC-F70DAB
defect, kabelsbezel Suzuki
Celerio

<https://www.advertentiax.nl/x-1992045-z>




PIONEER AVIC-F70DAB
defect, kabelsbezel Suzuki
Celerio

<https://www.advertentiax.nl/x-1992045-z>



PIONEER AVIC-F70DAB
defect, kabelsbezel Suzuki
Celerio

<https://www.advertentiax.nl/x-1992045-z>



PIONEER AVIC-F70DAB
defect, kabelsbezel Suzuki
Celerio

<https://www.advertentiax.nl/x-1992045-z>



PIONEER AVIC-F70DAB
defect, kabelsbezel Suzuki
Celerio

<https://www.advertentiax.nl/x-1992045-z>



PIONEER AVIC-F70DAB
defect, kabelsbezel Suzuki
Celerio

<https://www.advertentiax.nl/x-1992045-z>



PIONEER AVIC-F70DAB
defect, kabelsbezel Suzuki
Celerio

<https://www.advertentiax.nl/x-1992045-z>



PIONEER AVIC-F70DAB
defect, kabelsbezel Suzuki
Celerio

<https://www.advertentiax.nl/x-1992045-z>



PIONEER AVIC-F70DAB
defect, kabelsbezel Suzuki
Celerio

<https://www.advertentiax.nl/x-1992045-z>



PIONEER AVIC-F70DAB
defect, kabelsbezel Suzuki
Celerio

<https://www.advertentiax.nl/x-1992045-z>