Advertentienin

Urban Arrow E-bakfiets maxicosy adapters (requires repair)



Locatie Noord-Brabant

https://www.advertentiex.nl/x-2065464-z



The e-bike is from 2018, but the battery was replaced in 2022. The motor works very well.

The bike has a problem with the back wheel. The bike shop expert at the Spijkers Fietsen said that the hub of the wheel needs to be replaced. He estimated the repaired for €500.-

We would have repaired it but the shop has appointments only in two weeks and we're moving to another city next week. That's why we would like to sell it to someone who doesn't mind repairing it themselves, and we make a very good price for it.

Two bike keys, an charger and a receipt from the original purchase is included.

Maxicosy adapters can be de-installed.

Pick up near Wilhelminapark in.

	Urban Arrow E-bakfiets maxicosy adapters (requires repair)
	https://www.advertentiex.nl/x-2065 464-z
	Urban Arrow E-bakfiets maxicosy adapters (requires repair)
	https://www.advertentiex.nl/x-2065 464-z
	Urban Arrow E-bakfiets maxicosy adapters (requires repair)
殿龍	https://www.advertentiex.nl/x-2065 464-z
	Urban Arrow E-bakfiets maxicosy adapters (requires repair)
	https://www.advertentiex.nl/x-2065 464-z
	Urban Arrow E-bakfiets maxicosy adapters (requires repair)
	https://www.advertentiex.nl/x-2065 464-z
	Urban Arrow E-bakfiets maxicosy adapters (requires repair)
	https://www.advertentiex.nl/x-2065 464-z
	Urban Arrow E-bakfiets maxicosy adapters (requires repair)
	https://www.advertentiex.nl/x-2065 464-z
	Urban Arrow E-bakfiets maxicosy adapters (requires repair)
	https://www.advertentiex.nl/x-2065 464-z
	Urban Arrow E-bakfiets maxicosy adapters (requires repair)
	https://www.advertentiex.nl/x-2065 464-z
	Urban Arrow E-bakfiets maxicosy adapters (requires repair)
	https://www.advertentiex.nl/x-2065 464-z