

Cisco ASA 5510 (0 EUR)



Locatie **Gelderland, Arnhem**
<https://www.advertentiax.nl/x-65663-z>

Cisco ASA 5510 met volgende specs (show ver):

Cisco Adaptive Security Appliance Software Version 8.4(4)
 Device Manager Version 7.1(1)52

Compiled on Mon 21-May-12 10:48 by builders
 System image file is "disk0:/asa844-k8.bin"
 Config file at boot was "startup-config"

ciscoasa up 10 mins 8 secs

Hardware: ASA5510, 1024 MB RAM, CPU Pentium 4 Celeron 1600 MHz
 Internal ATA Compact Flash, 256MB
 BIOS Flash M50FW016 @ 0xffff00000, 2048KB

Encryption hardware device : Cisco ASA-55x0 on-board accelerator (revision 0x0)
 Boot microcode : CN1000-MC-BOOT-2.00
 SSL/IKE microcode: CNLite-MC-SSLm-PLUS-2.03
 IPSec microcode : CNLite-MC-IPSECm-MAIN-2.06
 Number of accelerators: 1

```

0: Vlan interface et0/0 : address is 649e.f335.5725
1: Vlan interface et0/1 : address is 649e.f335.5726
2: Vlan interface et0/2 : address is 649e.f335.5727
3: Vlan interface et0/3 : address is 649e.f335.5728
4: Ext: Management0/0 : address is 649e.f335.5725, irq 11
5: Int: Not used : irq 11
6: Int: Not used : irq 11
    
```

Licensed features for this platform:
 Maximum Physical Interfaces : Unlimited perpetual
 Maximum VLANs : 50 perpetual



<p>3-z https://www.advertentiax.nl/x-65666 Cisco ASA 5510</p>									

Inside Hosts : Unlimited perpetual
Failover : Disabled perpetual
VPN-DES : Enabled perpetual
VPN-3DES-AES : Enabled perpetual
Security Contexts : 0 perpetual
GTP/GPRS : Disabled perpetual
AnyConnect Premium Peers : 2 perpetual
AnyConnect Essentials : Disabled perpetual
Other VPN Peers : 250 perpetual
Total VPN Peers : 250 perpetual
Shared License : Disabled perpetual
AnyConnect for Mobile : Disabled perpetual
AnyConnect for Cisco VPN Phone : Disabled perpetual
Advanced Endpoint Assessment : Disabled perpetual
UC Phone Proxy Sessions : 2 perpetual
Total UC Proxy Sessions : 2 perpetual
Botnet Traffic Filter : Disabled perpetual
Intercompany Media Engine : Disabled