


Cisco C1111-4PLTEEA 4G LTE router met SFPgigabit poort (400 EUR)



Locatie **Noord-Holland, Heemskerk**
<https://www.advertentienx.nl/x-1018757-z>

Te koop aangeboden een Cisco C1111-4PLTEEA 4G LTE router met de volgende specificaties:

Cisco IOS XE Software, Version 16.06.04
 Cisco IOS Software [Everest], ISR Software (ARMV8EB_LINUX_IOSD-UNIVERSALK9_IAS-M), Version 16.6.4, RELEASE SOFTWARE (fc3)

ROM: IOS-XE ROMMON

Suite License Information for Module:'esg'

Suite Suite Current Type Suite Next reboot

FoundationSuiteK9 None None None
 securityk9
 appxk9

Technology Package License Information:

Cisco C1111-4PLTEEA 4G LTE router met SFPgigabit poort https://www.advertentienx.nl/x-1018757-z	Cisco C1111-4PLTEEA 4G LTE router met SFPgigabit poort https://www.advertentienx.nl/x-1018757-z	Cisco C1111-4PLTEEA 4G LTE router met SFPgigabit poort https://www.advertentienx.nl/x-1018757-z	Cisco C1111-4PLTEEA 4G LTE router met SFPgigabit poort https://www.advertentienx.nl/x-1018757-z	Cisco C1111-4PLTEEA 4G LTE router met SFPgigabit poort https://www.advertentienx.nl/x-1018757-z	Cisco C1111-4PLTEEA 4G LTE router met SFPgigabit poort https://www.advertentienx.nl/x-1018757-z	Cisco C1111-4PLTEEA 4G LTE router met SFPgigabit poort https://www.advertentienx.nl/x-1018757-z	Cisco C1111-4PLTEEA 4G LTE router met SFPgigabit poort https://www.advertentienx.nl/x-1018757-z	Cisco C1111-4PLTEEA 4G LTE router met SFPgigabit poort https://www.advertentienx.nl/x-1018757-z	Cisco C1111-4PLTEEA 4G LTE router met SFPgigabit poort https://www.advertentienx.nl/x-1018757-z
--	--	--	--	--	--	--	--	--	--

Technology Package License Information:

appxk9 None None None

securityk9 None None None

ipbasek9 Permanent ipbasek9

cisco C1111-4PLTEEA (1RU) processor with 1664045K/6147K bytes of memory.

Processor board ID GL22513NF

1 Virtual Ethernet interface

6 Gigabit Ethernet interfaces
2 Cellular interfaces
32768K bytes of non-volatile configuration memory.
4194304K bytes of physical memory.
2863103K bytes of flash memory at bootflash:.
0K bytes of WebUI ODM Files at webui:.

Configuration register is 0x2102

NAME: "Chassis", DESCR: "Cisco C1111-4PLTEEA Chassis"
PID: C1111-4PLTEEA , VID: V02

NAME: "Power Supply Module 0", DESCR: "External Power Supply Module"
PID: PWR-12V , VID: V01

NAME: "module 0", DESCR: "Cisco C1111-4PLTEEA Built-In NIM controller"
PID: C1111-4PLTEEA , VID:

NAME: "NIM subslot 0/0", DESCR: "Front Panel 2 port Gigabitethernet Module"
PID: C1111-2x1GE , VID: V01

NAME: "NIM subslot 0/1", DESCR: "C1111-ES-4"
PID: C1111-ES-4 , VID: V01

NAME: "NIM subslot 0/2", DESCR: "C1111-LTE Module"
PID: C1111-LTE , VID: V01

NAME: "module R0", DESCR: "Cisco C1111-4PLTEEA Route Processor"
PID: C1111-4PLTEEA , VID: V02 , SN: FOC224838KQ

NAME: "module F0", DESCR: "Cisco C1111-4PLTEEA Forwarding Processor"
PID: C1111-4PLTEEA , VID: , SN:

De router is eventueel in overleg met de laatste firmware te.