

Parrot CK3100 No Signal Reset Software Update (20 EUR)




Locatie **Noord-Holland, Amsterdam**
<https://www.advertentiax.nl/x-1290911-z>

Heeft u problemen met uw Parrot CK3100 carkit. Krijgt u de melding no signal of wordt uw telefoon niet herkend?

No Signal betekent dat er een probleem met de firmware is. Door de blauw box te resetten en te updaten naar de laatste uitgegeven firmware v5.00 wordt dit in 99 procent van de gevallen opgelost en kunt u weer handsfree bellen.

Ook wanneer uw telefoon niet wordt herkend kan een firmware update de oplossing zijn. De laatste uitgegeven firmware voor de ck3100 is v5.00

Wij kunnen bovenstaande voor uitvoeren voor EUR 20 incl..

 Parrot CK3100 No Signal Reset Software Update https://www.advertentiax.nl/x-1290911-z	 Parrot CK3100 No Signal Reset Software Update https://www.advertentiax.nl/x-1290911-z	 Parrot CK3100 No Signal Reset Software Update https://www.advertentiax.nl/x-1290911-z	 Parrot CK3100 No Signal Reset Software Update https://www.advertentiax.nl/x-1290911-z	 Parrot CK3100 No Signal Reset Software Update https://www.advertentiax.nl/x-1290911-z	 Parrot CK3100 No Signal Reset Software Update https://www.advertentiax.nl/x-1290911-z	 Parrot CK3100 No Signal Reset Software Update https://www.advertentiax.nl/x-1290911-z	 Parrot CK3100 No Signal Reset Software Update https://www.advertentiax.nl/x-1290911-z	 Parrot CK3100 No Signal Reset Software Update https://www.advertentiax.nl/x-1290911-z	 Parrot CK3100 No Signal Reset Software Update https://www.advertentiax.nl/x-1290911-z
--	---	---	---	--	---	---	---	---	---