

NTK OZA510-AU4 O2 sensor Hyundai Kia (42,96 EUR)



Locatie

Noord-Brabant, Cuijk

<https://www.advertentiax.nl/x-1749322-z>

Lengte 591mm; Lambda verwarmd; 4 leidingen * HYUNDAIGRANDEUR (XG)199812 -

/BodyEngineCCKWHPCylinderTypeYear30/300Otto29721381886Saloon199812 - / * HYUNDAISONATA Mk III (EF)199803 - 200505BodyEngineCCKWHPCylinderTypeYear2.0

16VOtto19971001364Saloon199806 - 2001102.4 16VOtto23511051434Saloon199803 - 200110 * HYUNDAITRAJET (FO)200003 -

/BodyEngineCCKWHPCylinderTypeYear2.0Otto19971001364MPV200003 - / * KIAOPTIMA (GD)200105

- /BodyEngineCCKWHPCylinderTypeYear2.0Otto19971001364Saloon200105 - /ManufacturerNumberDescriptionAL-KO0047 ()Shock AbsorberCARBOX10-8057 ()Rubber Tub, boot/ cargo bayCITROEN/PEUGEOT96369688 ()Lambda SensorFACET10.8057 ()Lambda

SensorHOFFER7481022 ()Lambda SensorMEAT & DORIA81022 ()Lambda SensorNGK0047 ()Lambda SensorNGKOZA510AU40047 ()Lambda probeNISSAN226A015700 ()Lambda

SensorNISSAN226A015705 ()Lambda SensorSEAT06E906265J ()Lambda SensorSKODA06E906265J ()Lambda SensorVAG06E 906 265 J ()Lambda SensorVEMOV10-76-0087 ()Lambda

SensorVOLKSWAGEN06E906265J ()Lambda Sensor

Websitewww.chargertech.nl/ntk-oza510-au4-o2-sensor-hyundai-kia.html?channable=4171d0696400343630307a&utm_campaign=marktplaats&utm_content=&utm_source=marktplaats.nl&utm_medium=cpc&am p=



NTK OZA510-AU4 O2 sensor
Hyundai Kia



NTK OZA510-AU4 O2 sensor
Hyundai Kia



NTK OZA510-AU4 O2 sensor
Hyundai Kia



NTK OZA510-AU4 O2 sensor
Hyundai Kia



NTK OZA510-AU4 O2 sensor
Hyundai Kia



NTK OZA510-AU4 O2 sensor
Hyundai Kia




NTK OZA510-AU4 O2 sensor
Hyundai Kia



NTK OZA510-AU4 O2 sensor
Hyundai Kia



NTK OZA510-AU4 O2 sensor
Hyundai Kia



NTK OZA510-AU4 O2 sensor
Hyundai Kia