

Laptop MSI GF63 Thin 10UC-476NL (250 EUR)




Locatie **Noord-Brabant**
<https://www.advertentieX.nl/x-1991159-z>



The laptop has suffered liquid damage in the sector of Enter, Backspace and adjacent keys on the keyboard. That liquid damage has not stopped it from working for over a year. Therefore, the motherboard must be intact.

Highly advised to be bought by a tech savvy person who can possibly pry it open and double check the condition of the motherboard and refurbish it if.

 Laptop MSI GF63 Thin 10UC-476NL https://www.advertentieX.nl/x-1991159-z	 Laptop MSI GF63 Thin 10UC-476NL https://www.advertentieX.nl/x-1991159-z	 Laptop MSI GF63 Thin 10UC-476NL https://www.advertentieX.nl/x-1991159-z	 Laptop MSI GF63 Thin 10UC-476NL https://www.advertentieX.nl/x-1991159-z	 Laptop MSI GF63 Thin 10UC-476NL https://www.advertentieX.nl/x-1991159-z	 Laptop MSI GF63 Thin 10UC-476NL https://www.advertentieX.nl/x-1991159-z	 Laptop MSI GF63 Thin 10UC-476NL https://www.advertentieX.nl/x-1991159-z	 Laptop MSI GF63 Thin 10UC-476NL https://www.advertentieX.nl/x-1991159-z	 Laptop MSI GF63 Thin 10UC-476NL https://www.advertentieX.nl/x-1991159-z	 Laptop MSI GF63 Thin 10UC-476NL https://www.advertentieX.nl/x-1991159-z
--	---	---	---	--	---	---	---	---	---