

MSI Optix MAG322CQRV Display beschadigd



Locatie **Limburg**
<https://www.advertentiex.nl/x-1120249-z>

Ik verkoop mijn MSI Optix MAG322CQRV beeldscherm omdat ik deze zelf zo niet meer kan gebruiken en een reparatie via MSI te duur is. Het scherm werkt nog wel, maar zoals je kunt zien zit er een zwart vlak in het beeld. De beschadiging zit in het paneel binnenin.

Zoals in de foto's te zien zitten alle originele accessoires nog bij het scherm en deze zijn nog als nieuw. Scherm zelf is nog geen 5 maanden gebruikt.

Accessoires:

- Power cord
- Power adapter
- HDMI kabel
- USB naar USB Type B kabel voor aansluiten op PC
- Voet + standaard
- Alle boekjes

Bon is desgewenst ook nog aanwezig, maar scherm valt buiten de garantie.

Specificaties:

- Panel Size 31.5" (80cm)
- Panel Resolution 2560 x 1440 (WQHD)
- Refresh Rate 144Hz

- Response time 1ms
- Refresh Rate 60Hz
- Resolution (pixels) 3840
- Viewing angle 178°
- Aspect ratio 16:9
- Curvature 1500R
- Contrast Ratio 3000:1
- OCR 10000000:1
- Active Display Area (mm) 697.34
- Pixel Pitch (H x V) 0.2724(H) x 0.2724(V)
- Surface Treatment Anti-glare
- Display Colors 16.7M



MSI Optix MAG322CQRV
Display beschädigt



MSI Optix MAG322CQRV
Display beschadigd

<https://www.advertentienx.nl/x-1120-249-z>




MSI Optix MAG322CQPV
Display beschadigd

<https://www.advertentia.nl/x-1120>
249-z



MSI Optix MAG322CQRV
Display beschadigd

<https://www.advertentia.nl/x-1120>
249-z



Display

- Contrast Ratio 8000:1
- Resolution 1920x1080
- Active Display
- Pixel Pitch 0.26mm
- Surface Treatment Anti-Glare
- Display Color 16.7M

Accessories

- Power Adapter 100W
- Power Cable 1.5m
- User Manual
- Warranty Card

Technical Specifications

- Model Number: HP Z8G2
- Part Number: 8000-0000
- Release Date: Q3 2023
- Country of Origin: Mexico

Additional Information

- This monitor is designed for professional use.
- It features advanced color calibration technology.
- The monitor is compatible with various operating systems.
- It includes multiple input ports for flexibility.

Contact Us

Email: sales@hp.com
Phone: +1 800 462 2769
Website: <https://www.hp.com>

HP Logo




MSI MAG32CQHV
Display beschadigt



ms Display 392.2560
MAG32CQrv beschädigd
https://www.gdverlentieix.nl/x-1120
4(H) x 2724(V)
249-z




<https://www.advertentie.nl/x-1120>
249-z



Display beschädigt

<https://www.advertentiax.nl/x-1120-249-z>



Display beschadigd

-
- DCI-P3 / sRGB 79% / Up to 100%
 - Video ports 1x DP (1.2)
 - 2x HDMI (2.0)
 - USB ports 2x USB 2.0
 - 1x USB 2.0 Type B (PC to Monitor)
 - Audio ports 1x Earphone out
 - Kensington Lock Yes
 - VESA Mounting 100 x 100 mm
 - Control 5-way OSD navigation joystick
 - Power Type External Adaptor 19V 4.74A
 - Power Input 100~240V, 50~60Hz
 - Power consumption 50W
 - Signal Frequency 70.56 to 214.56KHz (H)
 - 48 to 144Hz (V)
 - Adjustment (Tilt) -5° ~ 20°
 - Adjustment (Height) 0 ~ 130mm
 - Dimension (W x H x D) 710.38 x 513.6 x 266.5 mm / 27.95 x 20.11 x 10.33 inch
 - Weight (NW / GW) 7.3kg / 8.94kg
 - Frameless Design Yes
 - Console Mode FHD @