

Opel Corsa 1.2 16V 3D WR 2006 Zwart





Locatie **Limburg, Maastricht**
<https://www.advertentiax.nl/x-1235483-z>

Dealer onderhouden
 All-season banden
 Reservewiel
 Apk 10/2022
 Overige opties zie onderstaand

- Klapfunctie stoel defect
- Airco compressor defect
- lichte gebruiksschade)



 Opel Corsa 1.2 16V 3D WR 2006 Zwart https://www.advertentiax.nl/x-1235483-z	 Opel Corsa 1.2 16V 3D WR 2006 Zwart https://www.advertentiax.nl/x-1235483-z	 Opel Corsa 1.2 16V 3D WR 2006 Zwart https://www.advertentiax.nl/x-1235483-z	 Opel Corsa 1.2 16V 3D WR 2006 Zwart https://www.advertentiax.nl/x-1235483-z	 Opel Corsa 1.2 16V 3D WR 2006 Zwart https://www.advertentiax.nl/x-1235483-z	 Opel Corsa 1.2 16V 3D WR 2006 Zwart https://www.advertentiax.nl/x-1235483-z	 Opel Corsa 1.2 16V 3D WR 2006 Zwart https://www.advertentiax.nl/x-1235483-z	 Opel Corsa 1.2 16V 3D WR 2006 Zwart https://www.advertentiax.nl/x-1235483-z	 Opel Corsa 1.2 16V 3D WR 2006 Zwart https://www.advertentiax.nl/x-1235483-z	 Opel Corsa 1.2 16V 3D WR 2006 Zwart https://www.advertentiax.nl/x-1235483-z
--	---	---	---	--	---	---	---	---	---