


bakfiets (350 EUR)



Locatie **Noord-Holland, Amsterdam**
<https://www.advertentiex.nl/x-1375614-z>



Used Babboe 3 wheel bakfiets.
The saddle cannot be adjustd due to the seat post's rust, and the cover has holes(see image). (I use saddle cover to sit on.)
The gears don't work.
The chains are rusty but working.
The tires/wheels are in good condition.
Incl. 2 locks and rain cover included.
Above all, the bike works well as it's used them often and.

 https://www.advertentiex.nl/x-1375614-z bakfiets	 https://www.advertentiex.nl/x-1375614-z bakfiets	 https://www.advertentiex.nl/x-1375614-z bakfiets	 https://www.advertentiex.nl/x-1375614-z bakfiets	 https://www.advertentiex.nl/x-1375614-z bakfiets	 https://www.advertentiex.nl/x-1375614-z bakfiets	 https://www.advertentiex.nl/x-1375614-z bakfiets	 https://www.advertentiex.nl/x-1375614-z bakfiets	 https://www.advertentiex.nl/x-1375614-z bakfiets	 https://www.advertentiex.nl/x-1375614-z bakfiets
---	--	--	--	---	--	--	--	--	--