

Surface Pro 3 - Defect Model 1631 29-1 (50 EUR)



Locatie **Utrecht**
<https://www.advertentieX.nl/x-1812937-z>

Surface Pro 3 - Defect


Model 1631

In de tas is het een-an-ander mis gegaan
 glas van het scherm is kapot

wordt verkocht zonder voeding en zonder keyboard

lijkt het nog te doen, maar geen beeld



 Surface Pro 3 - Defect Model 1631 29-1 https://www.advertentieX.nl/x-1812937-z	 Surface Pro 3 - Defect Model 1631 29-1 https://www.advertentieX.nl/x-1812937-z	 Surface Pro 3 - Defect Model 1631 29-1 https://www.advertentieX.nl/x-1812937-z	 Surface Pro 3 - Defect Model 1631 29-1 https://www.advertentieX.nl/x-1812937-z	 Surface Pro 3 - Defect Model 1631 29-1 https://www.advertentieX.nl/x-1812937-z	 Surface Pro 3 - Defect Model 1631 29-1 https://www.advertentieX.nl/x-1812937-z	 Surface Pro 3 - Defect Model 1631 29-1 https://www.advertentieX.nl/x-1812937-z	 Surface Pro 3 - Defect Model 1631 29-1 https://www.advertentieX.nl/x-1812937-z	 Surface Pro 3 - Defect Model 1631 29-1 https://www.advertentieX.nl/x-1812937-z	 Surface Pro 3 - Defect Model 1631 29-1 https://www.advertentieX.nl/x-1812937-z
---	--	--	--	---	--	--	--	--	--